

2.5" HDD				SK-2500		FD-2500
Brand	Capacity	Model	Firmware	S2	400+	USB2
Hitachi	200GB	HDS721010KLA330		✓		
Hitachi	200GB	HTS722020K9SA00			✓	✓
Hitachi	500GB	HTS545050B9A300				✓
Intel	80GB	SSDSA2M080G2GC		✓		
Kingston	128GB	SSDNow V-Series		Note3		
OCZ	60GB	Vertex Series		✓		
Seagate	160GB	ST9160821AS	3.ALA	✓	✓	✓
Seagate	500GB	ST9500325AS	0001SDM1	✓		✓
Seagate	500GB	ST9500420ASG	0002SDM1			✓
WD	250GB	WD2500BEVT-22ZCT0				✓
WD	500GB	WD5000BEVT-75ZAT0	01.01A01	✓		✓
WD	500GB	WD5000BEVT-00AORT0	01.01A01	Note2		
WD	750GB	WD7500KEVT		Note3		

Updated:

1/25/2010

Key:


Compatible

Not Compatible

User reported not compatible

Notes:

- 1 User reported compatible
- 2 Jumper for RPS needs to be enabled
- 3 Power has to be turned on 5-10 seconds before connecting the interface cable to the computer

Remarks:

Do you have a drive that is not listed yet and would like to report it as compatible or incompatible, please drop us a mail at hddcompatibility@inxtron.com, thank you. None of your personal details will be disclosed and we will not reply to your e-mail but we appreciate the feedback and will include your drive in the next update.

3.5" HDD				PD-SATA			SK-3500		
Brand	Capacity	Model	Firmware	USB/GbE	Super-S Combo (Oxford 934)	S2	Super-S Combo	S2	U3
Hitachi	1TB	HDS721010KLA330		✓	✓		✓		✓
Hitachi	1TB	HDT721010SLA360							
Hitachi	2TB	HDS722020ALA330	20N					✓	✓
Intel	80GB	SSDSA2M080G2GC (SSD)	02G9						✓
OCZ	60GB	Vertex Series (SSD)							✓
Seagate	1TB	ST31000333AS	CC1H	✓			✓		
Seagate	1TB	ST31000340NS	SN06	✓	✓				✓
Seagate	1.5TB	ST31500341AS	SD17	✓	✓		✓		✓
WD	1TB	WD10EADS-00L5B1			✓		✓		
WD	1TB	WD1001FALS-00J7B1							✓
WD	2TB	WD20EADS-00S2B0						✓	
WD	2TB	WD20EADS-00R6B0			Note2	✓			✓
WD	2TB	WD20EARS-00S8B1					✓		

Updated:

5/26/2010

Key:

- ✓ Compatible
- ✗ Not Compatible
- ! User reported not compatible

Notes:




- 1 User reported compatible
- 2 Performance on 1394b lower than normal

Remarks:

Do you have a drive that is not listed yet and would like to report it as compatible or incompatible, please drop us a mail at hddcompatibility@inxtron.com, thank you. None of your personal details will be disclosed and we will not reply to your e-mail but we appreciate the feedback and will include your drive in the next update.

2 x 3.5" HDD				NT2					Taurus				
Brand	Capacity	Model	Firmware	Giga LAN	USB2	S2	800+	Super-S Combo	Super-S LCM	Super-S Combo	S2	LAN (PCB v1.2)	RAID II
Hitachi	160GB	7K160										✓	
Hitachi	250GB	HDT722525DLA380										✓	
Hitachi	1TB	HDS721010KLA330		✓	✓	✓	✓		✓			✓	
Hitachi	1TB	HDT721010SLA360						✓					
Maxtor	120GB	DiamondMax 10										✓	
Maxtor	200GB	DiamondMax Plus 9										✓	
Maxtor	500GB	DiamondMax 11										✓	
Samsung	80GB	SP0812C										✓	
Samsung	250GB	SP2504C										✓	
Samsung	500GB	HD501LJ										✓	
Samsung	1TB	HD103UJ										✓	
Samsung	1.5TB	HD154UI										!	
Seagate	160GB	ST3160811AS										✓	
Seagate	500GB	ST3500630AS										✓	
Seagate	750GB	ST3750640AS										✓	
Seagate	750GB	ST3750330AS										✓	
Seagate	1TB	ST31000340AS										✓	
Seagate	1TB	ST31000333AS								✓			✓
Seagate	1TB	ST31000340NS	SN06					✓		✓			
Seagate	1.5TB	ST31500341AS	SD17		✓	✓	✓	✓			✓	✓	
WD	80GB	WD800										✓	
WD	120GB	WD1200										✓	
WD	250GB	WD2500BEVT-22ZCT0										✓	
WD	500GB	WD5000AAJS										✓	
WD	500GB	WD5000AAKS-DOYGAO										✓	
WD	500GB	WD5000AAVS-22G9B1					✓						
WD	1TB	WD10EADS-00L5B1			✓		✓						
WD	2TB	WD20EADS-00R6B0		✓				✓	✓	✓	✓		

Updated:
11/30/2009

Key:
 Compatible
 Not Compatible
 User reported not compatible

Notes:
1 User reported compatible

Remarks:
Do you have a drive that is not listed yet and would like to report it as compatible or incompatible, please drop us a mail at hddcompatibility@inxtron.com, thank you. None of your personal details will be disclosed and we will not reply to your e-mail but we appreciate the feedback and will include your drive in the next update.






www.inxtron.com

4 x 3.5" HDD				Hydra				MD4	
Brand	Capacity	Model	Firmware	LAN	eSATA	Super-S LCM	Super-S Combo	eSATA	Super-S Combo (PCB 1.1)
Hitachi	1TB	HDS721010KLA330		✓	✓	✓	✓	✓	✓
Seagate	250GB	ST3250310AS					✓		
Seagate	1TB	ST31000333AS			✓		✓		✓
Seagate	1.5TB	ST31500341AS	SD17	✓	✓	✓	✓		✓
WD	500GB	WD5000AAJS-00TKAO		✓					
WD	500GB	WD5000ABYS-01YNA0		✓					
WD	500GB	WD5000AAKS-00YGA0		✓					
WD	1TB	WD10EADS-00L5B1	01.01A01			✓	✓		✓
WD	2TB	WD20EADS-00R6B0				✓			

Updated:
12/2/2009

Key:

-  Compatible
-  Not Compatible
-  User reported not compatible

Notes:

- 1 User reported compatible

Remarks:

Do you have a drive that is not listed yet and would like to report it as compatible or incompatible, please drop us a mail at hddcompatibility@inxtron.com, thank you. None of your personal details will be disclosed and we will not reply to your e-mail but we appreciate the feedback and will include your drive in the next update.